

CONFIDENTIAL

903304

NPIC/TDS/D/6-1729
20 December 1966

MEMORANDUM FOR THE RECORD

SUBJECT: Contract [REDACTED]

1. Upon further inspection of the light tables developed under the subject contract, certain deficiencies were discovered with regard to the microscope adapters.

2. Specifically, the adapter for the [REDACTED] Zoom 70 for light table #2 could not be collimated. [REDACTED] had not collimated it to the degree NPIC requires (10 minutes of arc) nor had they allowed for the adjustment. Since it was undesirable to send the light tables back to the contractor [REDACTED] and the undersigned modified the adapter by disassembling it and enlarging the mounting holes between the mounting block and the microscope ring. This effort required about five man hours.

3. The [REDACTED] adapter for light table #3 had been assembled incorrectly by [REDACTED] in that the focusing mechanism gear had been assembled backwards and serious damage to both the gear and its rack had occurred. This item is being returned to [REDACTED] for re-work.

[REDACTED]
Development Staff, TDS

Distribution:
Orig - Project File
2 - Chonos

pnf

DECLASS REVIEW BY NIMA / DoD

CONFIDENTIAL

GROUP 1
Excluded from automatic
downgrading and
declassification